

US-41 SOUTH SEWAGE PUMPING STATION REHABILITATION

HWEA – Crofton Utility Division

DECEMBER 2022

IMAGES OF EXISTING CONDITIONS

The following images were taken on September 14, 2022

These images are provided for reference to the HWEA and the Contractor.



Photo 1
Site with Gate, Wet Well, Valve Vault, Power Source, and Yard Hydrant



Photo 2
Site with Wet Well, Valve Vault, Power Source, and Yard Hydrant



Photo 3
Valve Vault No. 1



Photo 4
Valve Vault No. 2 – Interior with crushed stone bottom



Photo 5
Valve Vault No. 3 – Interior with crushed stone bottom



Photo 6
Wet Well No. 1 – Note broken hinge



Photo 7
Wet Well No. 2 – Note Single pump and missing guide rails



Photo 8
Wet Well No. 3 – Note Single pump and missing guide rails



Photo 9
Wet Well No. 4 – Overflow pipe to be plugged



Photo 10
Electrical No. 1



Photo 11
Electrical No. 2 – Control Panel Factory Decal



Photo 12
Electrical No. 3 – Control Panel Opened